

Issue Date: January 25, 2018

The purpose of this notification is to announce the obsolescence of the following products.

Part ID	Description
ALL TR-100 PARTS	All TR-100 parts including repair parts, caps, housings, gears, shafts, etc.

The Key Milestones in this obsolescence process are:

1. Formal Customer Notification of Obsolescence: **Immediately**
2. Orders for these products will no longer be accepted.

### **Reason for obsolescence**

The tool was replaced by the Torus 3D TR-130 and TR-200 cleaning tools. In an effort to keep our customers outfitted with the best possible tools, we are advancing our support and service to focus on the Torus product family.

### **Replacement part Options**

StoneAge will no longer support items for the above assemblies. Support parts are not available. Stoneage is continuing to offer a trade-in of any 3D for a discount on a TR-130 or TR-200. Please contact your local StoneAge sales representative for additional information.

### **Repairs**

StoneAge will no longer offer repair services after that time.

If you have any questions, please contact your account representative. Thank you.